

Article no.: M-3013



**Product data:**  
**Behälter 22.100 Liter aus V2A, isoliert,  
gebraucht,  
Standing**

EUR 13.200,00  
zzgl. 19 % MwSt. excl. shipping  
in stock: 1

Location: 33378 Rheda-Wiedenbrück

Behälter 22.100 Liter aus V2A, isoliert, gebraucht consists of the material 1.4301(AISI304) V2A. The volume is approx. 22,100 litres.

Behälter 22.100 Liter aus V2A, isoliert, gebraucht was last used in the following area: Foodstuffs.

1 pieces of Behälter 22.100 Liter aus V2A, isoliert, gebraucht is/are currently still available. Delivery can take place worldwide.

## Product description

### General

---

**Material in contact with product** 1.4301(AISI304) V2A

**Volume approx.** 22,100 litres

**Structure** Standing

**DIN design** unknown

**Year of manufacture** 1991

**Manufacturer** APV

**Condition** Used

## Dimensions approx.

---

**External diameter** 2600 mm  
**Cyl. height** 4650 mm  
**Foot height** 1100 mm  
**Total height** 6900 mm

## Design

---

**Weight approx.** 5000 kg  
**Weight per unit volume approx.** 1000 kg/m<sup>3</sup>  
**Insulation** No  
**Insulated area** Shell and floor  
**Insulation cladding** Fully welded stainless steel  
**Interior surface** Smoothed  
**Exterior surface** Smoothed  
**Floor type** Conical bottom  
**Head design** Conical bottom  
**Product chamber operating pressure** Atmospheric/unpressurised

## Equipment

---

**Temperature-controllable** No  
**Operating temperature** 140 °C

## Agitator

---

**Agitator quantity** 1 (piece)  
**Agitator position** Head off-centre  
**Agitator type** Wall scraper

## Supports

---

**Supports** Stainless steel feet  
**Number of feet** 5 (piece)

**Note on supports** höhenverstellbar, 1 Fuß leicht verbeult

## Fixtures and fittings

---

**Manway position** In head

**Outlet nozzle** 65

**Cleaning/CIP nozzle** in head

**Fixtures and fittings** Lifting lugs

**Additional fixtures and fittings** Air vent, Nameplate,

## Other notices

---


**Technical documentation** None

**Note** Vorhandene Heizmantel defekt, innen leicht braun  
angelaufen.

**Last usage** Foodstuffs

# Pictures





## Terms and conditions

The general terms and conditions of Georg Heuer Behälterhandel und Industribedarf GmbH apply. [View here.](#)